

Customer Service / Recalls and Upgrades

Recalls and Upgrades

View important firearm safety messages, warnings, upgrades, notices and recalls for Mossberg® Products.

**Maverick Hunter™ Over/Under Shotgun
Product Safety Warning and Recall Notice**

Mossberg model 1500, 1550 and 1700LS (Years 1970-1993)

SAFETY NOTICE

[Howa Machinery, Ltd.](#) of Japan is performing a safety upgrade on Mossberg model 1500, 1550 and 1700LS rifles produced by Howa between 1970 and 1993

Model 695® Bolt Action Shotgun (Years 1995-1996) - International Recall Details (includes Canada)

PRODUCT SAFETY WARNING AND RECALL NOTICE

O. F. Mossberg & Sons, Inc. is voluntarily recalling a limited number of its Model 695® bolt action shotguns. The recall is being initiated as a result of recent findings by company officials that a limited number of shotguns may discharge when closing the bolt during the loading of a live shell into the chamber.

The Mossberg Model 695® shotguns under recall were produced in 1995 and 1996, within serial numbers ranging from M000101 to M015304, inclusive. No other firearm models within the Mossberg product line are affected by the recall. Maverick® Model 95 bolt action shotguns within the identified serial number range are not affected.

WARNING: DO NOT LOAD OR USE YOUR MODEL 695® SHOTGUN

Consumers who purchased one or more of the shotguns falling within the affected serial number range should not load or use the shotgun, as an accidental firing may cause injury or death to the user or bystanders. Shotgun owners should not attempt to diagnose or repair the shotgun themselves.

Anyone (outside the U.S.A.) who currently owns or possesses a Model 695® shotgun within the recall range, or who purchased one and gave it or sold it to another party, should contact your local distributor immediately.

Please tap the International Distributor Locator link below to view our complete list of international distributors. These are the only distributors authorized to discuss and process the Model 695® recall. International distributors are listed by world regions and country. The information includes the distributor company name, telephone and fax number.

[International Distributor Locator](#)

We apologize for this inconvenience, but emphasize that this program will insure the safety of our Model 695® customers.

O. F. Mossberg and Sons, Inc.
P.O. Box 497
North Haven, CT 06473

Model 695® Bolt Action Shotgun (Years 1995-1996) - U.S.A. Recall Details

PRODUCT SAFETY WARNING AND RECALL NOTICE

O. F. Mossberg & Sons, Inc. is voluntarily recalling a limited number of its Model 695® bolt action shotguns. The recall is being initiated as a result of recent findings by company officials that a limited number of shotguns may discharge when closing the bolt during the loading of a live shell into the chamber.

The Mossberg Model 695® shotguns under recall were produced in 1995 and 1996, within serial numbers ranging from M000101 to M015304, inclusive. No other firearm models within the Mossberg product line are affected by the recall. Maverick Model 95 bolt action shotguns within the identified serial number range are not affected.

WARNING: DO NOT LOAD OR USE YOUR MODEL 695 SHOTGUN

Consumers who purchased one or more of the shotguns falling within the affected serial number range should not load or use the shotgun until it has been inspected and/or repaired at the factory, as an accidental firing may cause injury or death to the user or bystanders. Shotgun owners should not attempt to diagnose or repair the shotgun themselves.

Anyone (within the U.S.A.) who currently owns or possesses a Model 695 shotgun within the recall range, or who purchased one and gave it or sold it to another party, should contact the company immediately by calling the toll-free Product Service Number:

1-800-363-3555 (Monday through Friday 8AM - 4:30 PM Eastern)

We apologize for this inconvenience, but emphasize that this free inspection and repair program will insure the safety of our model 695® customers. To expedite the free inspection and recall repair program, we will send shipping tags to each customer and will cover all related shipping and repair charges. Please do not return your shotgun to the factory before contacting us using the toll-free number.



FIREARMS

[New Products](#)
[Handguns](#)
[Rifles](#)
[Shotguns](#)
[Pistol Grip / AOW / NFA Series](#)
[Dealers](#)
[Parts Schematics](#)
[FLEX Configurator](#)

STORE

[Parts](#)
[Apparel](#)
[Gear](#)

CUSTOMER SERVICE

[Firearm Service Request](#)
[Warranty Registration](#)
[Owner's Manuals](#)
[Parts Schematics](#)
[Request an Owner's Manual](#)
[Request a Catalog](#)
[Frequently Asked Questions](#)
[Recalls and Upgrades](#)
[Discontinued Models](#)

COMMUNITY

[About Mossberg](#)
[Trophy Room](#)
[Current Offers](#)
[Resources](#)

BLOG

[Advocacy](#)
[News & Events](#)
[Product Highlights](#)
[Tips & Tricks](#)

LAW ENFORCEMENT

[Armorer Training](#)
[Law Enforcement Distributors](#)
[Firearm Testing & Evaluation](#)
[Service & Support](#)

CONTACT US

[Safety](#)
[Press](#)
[Privacy Center](#)
[Privacy Policy](#)
[Terms of Use](#)



Safety and Safe Firearms Handling is Everyone's Responsibility



COOKIES ON THE MOSSBERG WEBSITE

We use cookies to help provide you with the best possible online experience. By using this site, you agree that we may store and access cookies on your device. Read our [Privacy Policy](#) to learn more about how we use cookies.

Continue